

C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

January 18, 2007

Adi Mihalache, Administrator Spaulding House 1709 Spaulding St Boise, ID 83705

License #: RC-743

Dear . Mihalache:

On December 27, 2006, a life safety code survey was conducted at Spaulding House. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely

TAYLOR BARKLEY

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

TB/slc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

January 11, 2007

Adi Mihalache, Administrator Spaulding House 1709 Spaulding St Boise, ID 83705

Dear Mr. Mihalache:

On December 27, 2006, a life safety code survey was conducted at Spaulding House. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by January 26, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

(X3) DATE SURVEY

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES

(X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED **IDENTIFICATION NUMBER:** A. BUILDING 01 - ENTIRE BUILDING B. WING 13R743 12/27/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 1709 SPAULDING ST **SPAULDING HOUSE BOISE, ID 83705** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE ID (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on December 27, 2006. The surveyor conducting the survey was: **Taylor Barkley** Health Facility Surveyor Facility Fire safety & Construction Bureau of Facility Standards TITLE (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

2M1T21

If continuation sheet 1 of 1



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

Facility Name	Physical Address	Phone Number
SPAULDING HOUSE	1709 Spaulding	208-384-1393
Administrator	City	ZIP Code
AdI MIHALACHE	BoisE Id	83705
Survey Team Leader	Survey Type	Survey Date
TAYLOR BARKIEY		12-27-06

1	AYIOK.	DAKKICY		19,0	1-06	
	-CORE ISSU	ES				
ITEM #	RULE# 16.03.22	等の場合を表現しています。 の対しました。 のがしました。 のがした。 のがしました。 のがした。	DESCRIPTION		DATE RESOLVED	BFS USE
2. 2.	410.02	Fire drills. The	facility only held one Fire d For the first shift. The re It per avarter.	r: 11:		
		dated 5-30-06 4	for the first shift. The re	ouremen	<u> </u>	
		is one drill per shi	it per avarter.			
9	250.10	Hot water temperature	. The facility has a temper	ture		
		of 134 degrees	The facility has a temperathe requirement is a temperation	ture	-	
		04 105 To 126		***************************************		
3.	405,01	The designal Tackellodian	and For in and Decimand	17 社 1		
<u>-</u>	1005,01	had an electrical ac	ord plugged into A multiple	Room		
		nowering A tv.	TO MORACA TOOLS A MOTHER	MORAPICK		
٠,						
						50 50 50 60 50 50
	se Required Date	Signature of Facility Representative			Date Signed 12 - 27 - 06 -	
ł "	27-07	Orther.			12.61.06.	